

FIG.1




FIG.2




FIG.3




FIG.4

The wire that is not used must be correctly insulated

SVUOTAMENTO  
EMPTYING  
VIDANGE  
LEEREN  
VACIADO  
VAZIO




FIG.5

RIEMPIMENTO  
FILLING  
REMPLISSAGE  
EINFÜLLEN  
LLENADO  
CHEIO




FIG.6

INSTALLAZIONE CONTRAPPESO  
INSTALLATION OF COUNTERWEIGHT  
INSTALLATION CONTREPOIDS  
MONTAGE DES GEGENGEWICHTES  
INSTALACIÓN CONTRAPESO  
INSTALAÇÃO DO CONTRAPESO

Температура среды: 50С

Пар. контактов: 220 В, 5А

